

Release Notes 02.30.0700

This document describes the changes in software version
02.30.0700 compared to the previous version 02.30.06.

Valid for:

- TOUCH800®
- TOUCH1200®
- TRACK-Guide III



Please note that after updating to version 02.30.0700, a downgrade to the previous version is only possible with support from Customer Service.

Please do not use installation packages of previous software versions.

System

Hardware V1.3.1

The system software now also supports new generation touch controllers installed in the TOUCH800® as of hardware version 1.3.1.

Note that when using TOUCH800® hardware version 1.3.1 and higher, at least software version 02.30.0700 must be used.

If an earlier software version is installed, the touch controller does not work. This problem can only be rectified by the technical customer service.

TRACK-Leader

SECTION-Control

Improved SECTION control behaviour when editing small gaps in the applied area, if the degree of overlap is 50% or 100%.

TRAMLINE-Management

Error messages have been adjusted.

Navigation

An error when using devices with connector but with incomplete geometry has been fixed.

TRACK-Leader AUTO®

NAV-900 Steering

Steering is no longer deactivated when the correction signal is changed to xFill or back.

NAV-900 Parallel guidance

Problems with unwanted lateral Offsets have been fixed.

Tractor-ECU

Calibration

The limit for the maximum value of a work position via the PTO speed has been increased to 999.

Virtual ECU

Designator	An incorrect identifier of the connector type in English language was corrected.
-------------------	--

General

NAV-900 RTX	RTX frequency configuration was adjusted to updated RTX frequencies.
NAV-900 xFill	An error in the xFill configuration has been fixed.
NAV-900 Guidance	Configuration parameters for tilt compensated positions (NAV-900 license Roll Corrected Manual Guidance) are also available in operation without automatic steering.
NAV-900 NMEA	The NMEA data output on the modem port is configurable again.
NAV-900 Firmware	The NAV-900 firmware version 11.20.063.4 is integrated in the installation V02.30.0700. The firmware of the NAV-900 is updated automatically.
AG-200 RTX	An error when configuring RTX frequencies has been fixed.
UT	AEF certification has been renewed for the ISO-UT and AUX-N functionalities. An error when loading multiple object pools simultaneously has been corrected.
TC	AEF certification has been renewed for the TC-BAS and TC-SC functionalities.
Demo licences	An error that could lead to sporadic crashes when demo licences were almost expired has been fixed.