

## Release Notes 02.30.08

This document describes the changes in software version **02.30.08** compared to the previous version 02.30.0700.

Valid for:

- TOUCH800®
- TOUCH1200®
- TRACK-Guide III



Note that after updating to version 02.30.08, a downgrade to version 02.30.07 or older is only possible with the support from Customer Service.

Please do not use installation packages of previous software versions.

### ISOBUS-TC

---

<b>SECTION-Control</b>	The number of sections was previously limited to 200. Now the maximum number of 254 specified by the ISOBUS standard is possible.
------------------------	---

---

### TRACK-Leader

---

<b>TRAMLIN-Management</b>	ISO/AEF have released a new version of the TRAMLIN-Management documentation (V1.13-v1). Some previously proprietary DDIs are now official. These have now been integrated. The proprietary DDIs are still supported as well.
---------------------------	--

---

### TRACK-Leader AUTO®

---

<b>NAV-900 Steering</b>	When steering on a guidance line in a tight curve, the guidance line actually driven did not match the guidance line displayed. The vehicle started exactly on the displayed guidance line, but later steered away from the displayed guidance line and drove up to 40 cm beside the displayed guidance line. However, the NAV-900 thought it was steering exactly on the guidance line. This error has been fixed.
-------------------------	---

---

<b>NAV-900 Parallel guidance</b>	If you are working with the NAV/TOUCH steering system and pressed remote activation or on-screen activation immediately after activating a new guidance line (highlighted in blue) in TRACK-Leader, error 122 was displayed. This error has been fixed.
----------------------------------	---

---

## General

---

<b>NAV-900 Firmware</b>	The NAV-900 firmware version 13.00.002.4 is integrated in the installation V02.30.08. The firmware of the NAV-900 is updated automatically.
<b>Display of error messages</b>	Under certain conditions there was an error in the display of error messages. These are now displayed correctly.
<b>Ukrainian keyboard layout</b>	The display of the keyboard layout and some characters has been corrected.

---