

Release Notes 07.09.04.12

This document describes the changes in software version **07.09.04.12** compared to the previous version 07.09.04.01.

Valid for:

- SPRAYER-Controller MAXI 3.0
- SPRAYER-Controller MIDI 3.0



NOTICE

Software update for other components

First update the software for the primary job computer before you update the software for other components.

After updating the primary job computer, install the respective software versions listed in the table.

System requirements

| Component | Item number | Minimum software version |
|---|-------------|--------------------------|
| SPRAYER-Controller MIDI 3.0 as secondary job computer | 3032245601 | 07.09.04.12 |
| TANK-Control II OEM | 30532450 | 01.03.01.00 |
| TANK-Control II OEM | 30609410 | 01.03.01.00 |
| TANK-Control II OEM | 30627300 | 01.03.01.00 |
| DISTANCE-Control II ME | 30303165 | 01.00.10.02 |
| DISTANCE-Control II ME | 3030316501 | 01.00.10.02 |
| External keypad | 30303155 | 7.1J |
| Individual nozzle switching EDS | 3030308530 | 01.00.05 |

Bug fixes

| | |
|---------------------------|---|
| TANK-Control | The status when filling the tank is now displayed correctly. |
| ISOBUS Data Logger | Communication with an ISOBUS Data Logger no longer causes the machine to shut down. |
| ISOBUS-TC | The counter readings are now processed correctly. |